


1-0011
no.5



Digitized by the Internet Archive
in 2012 with funding from
University of Illinois Urbana-Champaign

<http://archive.org/details/mixinginturbulen00univ>

FIFTH QUARTERLY PROGRESS REPORT ON RESEARCH

carried out by the

ENGINEERING EXPERIMENT STATION

of the

UNIVERSITY OF ILLINOIS

for

THE BIOLOGICAL DEPARTMENT, ARMY CHEMICAL CORPS, CAMP DETRICK

on

Contract DA-18-064-CIL-445

Order No. 474-1


October 1, 1951, through December 31, 1951

MIXING IN TURBULENT FLOW

Prepared by: Arnold Kivnick

Copies:

- 8 - Technical Director, Biological Department
Camp Detrick, Frederick, Maryland
- 1 - Director, Eng. Expt. St., Univ. of Illinois
- 1 - Chairman, Graduate Research Board, U. Of I.,
Chemistry Department, U. Of I.
- 20 - Files



$\frac{1}{2} \left(\frac{1}{2} \right)^2 = \frac{1}{8}$

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100 101 102 103 104 105 106 107 108 109 110 111 112 113 114 115 116 117 118 119 120 121 122 123 124 125 126 127 128 129 130 131 132 133 134 135 136 137 138 139 140 141 142 143 144 145 146 147 148 149 150 151 152 153 154 155 156 157 158 159 160 161 162 163 164 165 166 167 168 169 170 171 172 173 174 175 176 177 178 179 180 181 182 183 184 185 186 187 188 189 190 191 192 193 194 195 196 197 198 199 200 201 202 203 204 205 206 207 208 209 210 211 212 213 214 215 216 217 218 219 220 221 222 223 224 225 226 227 228 229 230 231 232 233 234 235 236 237 238 239 240 241 242 243 244 245 246 247 248 249 250 251 252 253 254 255 256 257 258 259 260 261 262 263 264 265 266 267 268 269 270 271 272 273 274 275 276 277 278 279 280 281 282 283 284 285 286 287 288 289 290 291 292 293 294 295 296 297 298 299 300 301 302 303 304 305 306 307 308 309 310 311 312 313 314 315 316 317 318 319 320 321 322 323 324 325 326 327 328 329 330 331 332 333 334 335 336 337 338 339 340 341 342 343 344 345 346 347 348 349 350 351 352 353 354 355 356 357 358 359 360 361 362 363 364 365 366 367 368 369 370 371 372 373 374 375 376 377 378 379 380 381 382 383 384 385 386 387 388 389 390 391 392 393 394 395 396 397 398 399 400 401 402 403 404 405 406 407 408 409 410 411 412 413 414 415 416 417 418 419 420 421 422 423 424 425 426 427 428 429 430 431 432 433 434 435 436 437 438 439 440 441 442 443 444 445 446 447 448 449 450 451 452 453 454 455 456 457 458 459 460 461 462 463 464 465 466 467 468 469 470 471 472 473 474 475 476 477 478 479 480 481 482 483 484 485 486 487 488 489 490 491 492 493 494 495 496 497 498 499 500 501 502 503 504 505 506 507 508 509 510 511 512 513 514 515 516 517 518 519 520 521 522 523 524 525 526 527 528 529 530 531 532 533 534 535 536 537 538 539 540 541 542 543 544 545 546 547 548 549 550 551 552 553 554 555 556 557 558 559 560 561 562 563 564 565 566 567 568 569 570 571 572 573 574 575 576 577 578 579 580 581 582 583 584 585 586 587 588 589 590 591 592 593 594 595 596 597 598 599 600 601 602 603 604 605 606 607 608 609 610 611 612 613 614 615 616 617 618 619 620 621 622 623 624 625 626 627 628 629 630 631 632 633 634 635 636 637 638 639 640 641 642 643 644 645 646 647 648 649 650 651 652 653 654 655 656 657 658 659 660 661 662 663 664 665 666 667 668 669 670 671 672 673 674 675 676 677 678 679 680 681 682 683 684 685 686 687 688 689 690 691 692 693 694 695 696 697 698 699 700 701 702 703 704 705 706 707 708 709 710 711 712 713 714 715 716 717 718 719 720 721 722 723 724 725 726 727 728 729 730 731 732 733 734 735 736 737 738 739 740 741 742 743 744 745 746 747 748 749 750 751 752 753 754 755 756 757 758 759 760 761 762 763 764 765 766 767 768 769 770 771 772 773 774 775 776 777 778 779 780 781 782 783 784 785 786 787 788 789 790 791 792 793 794 795 796 797 798 799 800 801 802 803 804 805 806 807 808 809 810 811 812 813 814 815 816 817 818 819 820 821 822 823 824 825 826 827 828 829 830 831 832 833 834 835 836 837 838 839 840 841 842 843 844 845 846 847 848 849 850 851 852 853 854 855 856 857 858 859 860 861 862 863 864 865 866 867 868 869 870 871 872 873 874 875 876 877 878 879 880 881 882 883 884 885 886 887 888 889 890 891 892 893 894 895 896 897 898 899 900 901 902 903 904 905 906 907 908 909 910 911 912 913 914 915 916 917 918 919 920 921 922 923 924 925 926 927 928 929 930 931 932 933 934 935 936 937 938 939 940 941 942 943 944 945 946 947 948 949 950 951 952 953 954 955 956 957 958 959 960 961 962 963 964 965 966 967 968 969 970 971 972 973 974 975 976 977 978 979 980 981 982 983 984 985 986 987 988 989 990 991 992 993 994 995 996 997 998 999 1000 1001 1002 1003 1004 1005 1006 1007 1008 1009 1010 1011 1012 1013 1014 1015 1016 1017 1018 1019 1020 1021 1022 1023 1024 1025 1026 1027 1028 1029 1030 1031 1032 1033 1034 1035 1036 1037 1038 1039 1040 1

1. *Phragmites australis* (Cav.) Trin. ex Steud.

[illegible]

1940

... ..

1890

U.S. DEPT. OF AGR. Wash., D.C. 20250

1. The first of the three, and the most important, is the fact that the Government has not been able to get the necessary amount of money to carry on its operations. This is due to the fact that the Government has not been able to get the necessary amount of money to carry on its operations. This is due to the fact that the Government has not been able to get the necessary amount of money to carry on its operations.

532.5

Ill m.

no. 5

ENGINEERING
LIBRARY

MIXING IN TURBULENT FLOW

I. Summary

The technical report on the single heated jet confined in a duct has been completed, and will be distributed shortly. Work is progressing on the preparation of technical reports on dual isothermal jets with axes at an angle to one another, the electronic system of a hot-wire anemometer and studies of turbulent transport of heat in ducts, and the application of the Reichardt hypothesis to the transport of momentum and mass in coaxial gas jets.

The hot-wire anemometer has been moved to a new location in order to secure an oil-free air supply. Experimental studies on calibration coefficients of impact tubes are in progress. The computation of the extent of coalescence of droplets in turbulent free jets has been submitted to the Biological Department of the Army Chemical Corps for consideration. Experimental studies on the pneumatic thermometer and the high-velocity spray dryer are continuing.

The present contract expires on 31 December, 1951. Technical reports now in preparation will be issued as they are completed. A final summary report must necessarily await the completion of the technical reports.

The experimental work on the high-velocity spray dryer and the pneumatic thermometer will be carried to completion without additional support. When the experiments are complete, they will be covered in a technical report. The experiments involving impact tubes will be continued with support from the Office of Naval Research and the Flight Research Laboratory. When the studies covered in this proposal have been completed, they will be presented as a technical report to the Chemical Corps. The report covering the studies on coalescence of droplets awaits the decision of the Biological Division as to whether or not the recommended computation should be performed. If not, the technical report covering the work done will be prepared forthwith.

II. Background

The general objective of this program has been to investigate the mixing of fluid streams in turbulent jets. The free jet, the enclosed jet, and intersecting jet were the cases considered. The data resulting from fundamental studies were to be applied to atomization of liquids in gas streams and to processes involving the mixing of droplets and gases in jets and ducts, accompanied by the transport of momentum, heat, and mass.

III. Progress during the period covered by this report

a. Dual Isothermal Jets with Axes at an Angle to One Another

A technical report on this is in preparation .

b. Single Heated Jet Confined in A Duct

A technical report has been prepared, and will be distributed shortly.

c. Turbulent Transport of Heat in Ducts

The foremost problem impeding progress in this study has been the presence of oil in the air stream. An attempt was made to remove the oil by the use of high-pressure porous ceramic filters, and by low-pressure glass-battling air filters. Although the oil content was appreciably reduced by these methods, the air finally produced still contained too much oil to permit satisfactory operation of the hot wire anemometer. Moreover, because of the presence in the Air-Flow Laboratory of high-speed turbo-superchargers which operated at a prohibitively high noise level, it was decided to remove the anemometer and related equipment from the Air-Flow Laboratory, and to locate in the Projects Laboratory of the East Chemistry Building, on the University Campus in Urbana. A centrifugal blower was located and tested, and found to be a suitable air supply. The anemometer was dismantled, moved, and reassembled at its new site. It remains now to build the ducting and flow system needed for further experiments.

The technical report covering the work described in the Fourth Quarterly Progress Report is being prepared by R. W. Kunstman in conjunction with his doctoral dissertation. Further work with the anemometer will be reported in technical reports to the Office of Naval Research and the Flight Research Laboratory, which will support this research in the coming year.

d. High-Velocity Spray Dryer

The problems of instrumentation described in the Fourth Quarterly Progress Report have been attacked, and, it is believed, surmounted. The measurement of humidity was performed by an addition to the pneumatic thermometer (cf. section e-2, Instruments). The air stream was dried through a bed of magnesium perchlorate, an extremely effective desiccant; and the dried stream was then passed through a calibrated orifice. The humidity may be calculated by the difference in the volume of the moist and dried air streams.

The first drying runs, in which water droplets are evaporated, have recently been undertaken.

e. Instruments

1. The total head impact tube (Pitot Tube)

And in the year 1881...

Individuals of the same name...

And in the year 1882...

And in the year 1883...
And in the year 1884...
And in the year 1885...
And in the year 1886...
And in the year 1887...
And in the year 1888...
And in the year 1889...
And in the year 1890...
And in the year 1891...
And in the year 1892...
And in the year 1893...
And in the year 1894...
And in the year 1895...
And in the year 1896...
And in the year 1897...
And in the year 1898...
And in the year 1899...
And in the year 1900...

And in the year 1901...
And in the year 1902...
And in the year 1903...
And in the year 1904...
And in the year 1905...
And in the year 1906...
And in the year 1907...
And in the year 1908...
And in the year 1909...
And in the year 1910...

And in the year 1911...

And in the year 1912...
And in the year 1913...
And in the year 1914...
And in the year 1915...
And in the year 1916...
And in the year 1917...
And in the year 1918...
And in the year 1919...
And in the year 1920...

And in the year 1921...
And in the year 1922...

The experimental program concerned with the investigation into the calibration coefficients of impact tubes has been delayed by the unforeseen occurrence of leaks in the airflow system. Since these leaks were present in the part of the system between the flow meter and the equipment to be used in this investigation, and since the leaks were in heat exchange equipment which could neither be repaired nor removed from the line, it has been necessary to build a new flow meter, of the orifice type, and to locate it downstream of the leaks. This meter is now undergoing calibration. When this work is completed, it will be possible to return to the study on impact tubes.

In the interim, the literature search has been broadened and intensified, to determine whether the approach being taken in this research has ever been used before. In particular, recent studies are being evaluated.

The experimental program will be continued with the support previously mentioned. When that part of the research covered under this contract has been completed, a technical report will be prepared.

2. Dry Bulb Temperature Probe (Pneumatic Thermometer)

Repeated attempts to operate as critical orifices the several orifices of which the pneumatic thermometer is composed have failed because of lack of capacity of the pumps concerned. In order to avoid further loss of time and expense in securing a suitable vacuum pump, the pumps available have been operated submerged in ice, to prevent overheating and resultant severe damage. Since the orifices could not be operated at the critical pressure drop, it was necessary to calibrate each orifice. This was done by passing an air stream through one of a set of precision Flowmeters, and then through the orifices.

Much of the experimental work during this period has been concerned with establishing the precise limits of accuracy permitted by the unavoidable errors in the apparatus. As an example of the nature of these errors, fourteen observations of manometers are required for the determination of each point. Taking into account the error inherent in each of these observations, a careful variance analysis shows that the probable error in any single observation of temperature is 3 percent. Since the readings will be in the region of 1000°R., the error will be about 30°F. out of about 600°F. However, these observational errors should be eliminated or materially reduced by the smoothing procedures to be employed in the course of operating the instrument. Although the value of any one observation may vary from the true reading by as much as 30°F., there should be far less variation in the mean value of ten such readings. The variation in the mean value has been found to be a

a function of the variation of the orifice coefficients with the gas flow rate. In evaluating the orifice coefficients, 219 separate runs were performed. They indicate that the maximum variation in orifice coefficients is of the order of 3 percent while the standard deviation of those coefficients from their mean value is 1.5 percent. Therefore, the standard deviation between successive readings of temperature obtained from the pneumatic thermometer should be not more than 15°F. in 1000°R. , or 15°F. in about 600°F. This is satisfactory precision for engineering studies.

The pneumatic thermometer was further complicated by being modified in order to provide a humidity measurement. A third orifice was added to the line. Thoroughly desiccated air is passed through this last orifice and metered, and its flow rate is compared with that through the second orifice; from these two flow rates, the humidity of the gas flowing through the second orifice may be computed.

Barring unforeseen difficulties, the pneumatic thermometer may be used with reasonable assurance of accuracy within the limits specified.

f. Theoretical Program

The problem of coalescence of droplets in a turbulent jet was submitted to three computation laboratories, in order that estimates might be made of the cost of computing the solution. The laboratories were the Differential Analyzer Laboratory of the University of Pennsylvania, the Punched-Card Digital Computer Laboratory of the Department of Chemical Engineering at the Pennsylvania State College, and the Computer Laboratory of the National Bureau of Standards. The last named group has submitted as an estimate \$5,000, while neither of the other groups has as yet been able to decide on the probable expense. Since the funds assigned to this contract are virtually exhausted, the matter of the computation has been turned over to the Biological Department together with all information necessary for the solution.

In the event that the Department prefers not to go ahead with the computation at this time, a technical report on the coalescence of droplets in turbulent jets will be prepared, in which the equations will be presented in their final form, together with all information necessary for the solution.

The extension of the Reichardt hypothesis to the flux of momentum and mass in the case of a jet issuing into a stream flowing in a duct has been completed. A technical report on this subject is in the last stages of preparation, and should be issued before the end of January, 1952.

IV. Personnel

The project has been under the supervision of Dr. Arnold Kivnick on a full-time basis; Professor H. F. Johnstone has replaced Professor E. W. Conings in the position of overall direction. During the period covered in this report, C. L. Coldren was employed on a half-time basis, on the high-velocity spray dryer. J. E. Romano worked on the hot-wire anemometer, and R. D. Danielson on the impact-tube studies; neither of these received compensation from the contract.

UNIVERSITY OF ILLINOIS-URBANA



3 0112 073926682